OFFICE OF THE SUB DIVISIONAL OFFICER P.W.D. SUB DIVISION KURUD

No. 781 /SDC

DATE: 23.06.2023

CERTIFICATE

This is to certify thet we have inspected Kendriya Vidyalaya Kurud, the structure of the school building is safe for the academic activities, also inspected all the electrical equipments and control panel in the Kendriya Vidyalaya Kurud on dated 23.06.2023 And found that the electrical equipments and control panel are working properly.

Sub Divisional Officer
P.W.D. Sub Division Rurud
Distt. Dhamtari (C.G.)

SUB DIVISIONAL OFFICER

प्राचार्य Principal केन्द्रीय विद्यालय /Kendriya Vidyalaya कुरूद /KURUD जिला धमतरी /District DHAMTARI पिन /Pin 493663 (छ.ग./C.G.)